Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080064-3

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11919

RECEIVED FROM

DATE REC'D. 4-15-57

P.O. NO.

VENDOR PACKING SLIP NO.

Plant #9

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	C	21	C	13	2				

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
20	731458 "B" Disc Tiner	20		New Stock

IP) #5582

RECEIVED BY [illegible] | INSPECTED BY [illegible] | DATE 4-15-57 | REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11953

RECEIVED FROM

DATE REC'D. 4-18-57

P.O. NO.

VENDOR PACKING SLIP NO.

Plant #9

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322		459	C	20					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
12	731239 "E" Cam Clutch	12		No Stops

IP #5600

RECEIVED BY [illegible] | INSPECTED BY [illegible] | DATE 4-19-57 | REJECTS RETURNED ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080064-3

HMC-1065